UNITED KINGDOM

SIDEWAY-FORCE SKID RESISTANCE SURVEY DEVICES ACCREDITATION TRIAL SUMMARY TEST CERTIFICATE

Report No: 0127SKID/S66 HSL Issue 4

REGISTRATION NUMBER: S66 HSL TRIAL Reference No: 16

Operated by PTS

Of Britannia House, 1 Rough Hey Road, Grimsargh, Preston

has participated in a United Kingdom Sideway-Force Coefficient Routine Investigation Machine Accreditation trial on **12 April 2022** at HORIBA-MIRA Proving Ground, Watling Street, Nuneaton, Warwickshire, CV10 0TU under the supervision of TRL.

The above machine has been tested against the criteria specified in Accreditation and Quality Assurance of Sideway-force Skid Resistance Survey Devices document¹ issue 4.1.

This machine has successfully met the mandatory criteria. Some Network Authorities may also require specific level of performance in some or all of the additional tests. The performance of this machine in each test is summarised in the Annex to this test certificate.

This certificate supersedes any previous certificates issued by TRL.

Signed on behalf of TRL Limited

Patrick Werro

Valid From:14 April 2022Date of expiry:14 May 2023

¹ This document is available from TRL or from the following website <u>https://ukrlg.ciht.org.uk/ukrlg-home/guidance/road-condition-information/data-</u><u>collection/skid-resistance/</u>



0127SKID/S66 HSL Issue 4

Page 1 of 2

Test Certificate Annex

The following parameters must be passed to successfully meet the requirements of the accreditation trial.

Tested Parameter	Left wheel	Right wheel	
Skid Resistance			
Between run standard deviation	Pass	No Data Supplied	
Between equipment standard deviation	Pass	No Data Supplied	
Distance measurement and Vehicle Speed			
Distance measured	Pass*		
Vehicle Speed		Pass	
Test wheel weight and water flow			
Test wheel weight	202.3	No Data Supplied	
Water flow rate	Pass	No Data Supplied	
Water flow direction	Pass	No Data Supplied	
* Comments:			

The device did not meet the requirements for distance measured on the official test site (twin horizontal straights at MIRA). However, the measurements from the device were consistent between runs and it also exhibited a better performance on the other test sites. Therefore it is deemed that there is not a systematic issue with the system but that it was not correctly calibrated at the trials.

The following parameters were also tested/reviewed. They are not currently mandatory requirements, however some Network Authorities may also require specific level of performance in some or all of these additional tests.

Tested Parameter	Performance	
OSGR coordinate measurement	Not Suitable	
Altitude measurement	Low	
Data alignment performance	Satisfactory	
.S10 file format	Satisfactory	
.LOC file format	Satisfactory	
.RCD file format	Satisfactory	
.BCD file format	Satisfactory	
Comments:		

OSGR assessed against OSGR fitted and push button criteria on two live test routes.

0127SKID/S66 HSL Issue 4

This certificate remains the property of TRL Limited and can be verified by emailing <u>accreditation&qa@trl.co.uk</u> TRL Ltd Crowthorne House, Nine Mile Ride, Wokingham, RG40 3GA 121