UNITED KINGDOM

SIDEWAY-FORCE SKID RESISTANCE SURVEY DEVICES ACCREDITATION TRIAL SUMMARY TEST CERTIFICATE

Report No: 0122SKID/KX07 YXH Issue 9

REGISTRATION NUMBER: KX07 YXH
TRIAL Reference No: 21

Operated by **Surrey County Council**Of Merrow Laboratory, Merrow Lane, Guilford

has participated in a United Kingdom Sideway-Force Coefficient Routine Investigation Machine Accreditation trial on **12 April 2022** at HORIBA-MIRA Proving Ground, Watling Street, Nuneaton, Warwickshire, CV10 0TU under the supervision of TRL.

The above machine has been tested against the criteria specified in Accreditation and Quality Assurance of Sideway-force Skid Resistance Survey Devices document¹ issue 4.1.

This machine has successfully met the mandatory criteria. Some Network Authorities may also require specific level of performance in some or all of the additional tests. The performance of this machine in each test is summarised in the Annex to this test certificate.

This certificate supersedes any previous certificates issued by TRL.

Signed on behalf of TRL Limited

Patrick Werro

Valid From: 14 April 2022 Date of expiry: 14 May 2023

¹ This document is available from TRL or from the following website https://ukrlg.ciht.org.uk/ukrlg-home/guidance/road-condition-information/data-collection/skid-resistance/



Test Certificate Annex

The following parameters must be passed to successfully meet the requirements of the accreditation trial.

Tested Parameter	Left wheel	Right wheel	
Skid Resistance			
Between run standard deviation	Pass	No Data Supplied	
Between equipment standard deviation	Pass	No Data Supplied	
Distance measurement and Vehicle Speed			
Distance measured	Pass		
Vehicle Speed	Pass		
Test wheel weight and water flow			
Test wheel weight	200.3	No Data Supplied	
Water flow rate	Pass	No Data Supplied	
Water flow direction	Pass	No Data Supplied	
* Comments:			

The following parameters were also tested/reviewed. They are not currently mandatory requirements, however some Network Authorities may also require specific level of performance in some or all of these additional tests.

Tested Parameter	Performance	
OSGR coor <mark>dinate mea</mark> surement	No Data Supplied	
Altitude measurement	No Data Supplied	
Data alignment performance	Satisfactory	
.S10 file format	Satisfactory	
.LOC file format	Satisfactory	
.RCD file format	No Data Supplied	
.BCD file format	No Data Supplied	
Comments:		



0122SKID/KX07 YXH Issue 9 Page 2 of 2